## Old Sneddon Street Paisley **Network Rail Business Space Arch inspection Occupied Property**



Commercial Property Maintenance Services Ltd



Property before work commenced.



Fylon sheeting fitted to the Upper roof area to prevent water ingress which will prevent future problems to the tenant.

## **ARCH STRIP OUT** AND REFURBISH



Front counter area after hand-back.









