



Balustrade Repairs Network Rail Station Improvement



Commercial Property Maintenance Services Ltd



Bridge with Temporary panelling



Completed Balustrading



Completed Balustrading and DDA compliant handrail

BALUSRADE REPLACEMENT

Following an accident where a child fell through the balustrading of a footbridge a programme of works was prepared to prevent this happening again.

The works comprised the following:-

- Initially install temporary timber panelling to similar bridges to eliminate the threat of this problem
- Arrange for a specification to be drawn up and approved to replace the balustrading.
- Fabricate and install new compliant galvanised balustrading complete with DDA hand -railing.
- Arrange suitable station and track access as required to complete the works.
- Works completed to time and budget.