

Culvert grating fabrication & installation Network Rail Caldercruix, Airdrie to Bathgate Line.

CPMS were contacted by a Network Rail Property representative advising a fault/incident had been reported through the operational help desk.

A lineside neighbour of the Airdrie to Bathgate rail line had advised one of his cattle had become lodged and subsequently died in a large under track drainage culvert, during a period of heavy rain.

With this being a distressing event for the neighbour and his family, he was determined that there would not be a repeat of this situation.

CPMS understood the severity and urgency of the fault and immediately attended site to obtain measurements for a new culvert grating and to instruct the fabrication to be commenced as soon as possible.

Within a week of receiving the fault, CPMS had measured, fabricated, galvanised and installed the grating to the culvert on site.

Works were completed significantly quicker than either Network Rail or the Landowner expected, with both highly praising the workmanship and delivery time achieved by the CPMS team.

Completed galvanized steel grating fixed to culvert mouth

